PPE Dedicated Supply Channel

Important Customer Alert

Type IIR masks – Cardinal Health Product Concerns

ICA: 002

Date: 22/05/2020

Alert:

- There have been five separate complaints raised regarding the Cardinal Health Type IIR Masks. An initial investigation has occurred which has determined that there is a product fault with a small number of lots, either with the stitching on the ties or with the foam nose strip.
- This product has been issued through:
 - o PPE Push
 - o PPE Portal
 - o LRF Pushes

Product Affected:

There is one product impacted

- Mask, Type IIR
- Supplier: Cardinal Health
- NPC: BWM028MPC: AT74535

Lots Affected

The stitching coming away on the ties relates to five lots:

- 0508MLP09
- 0511MLP09
- 0513MLP09
- 0529MLP09
- 0531KLP09.

•

The material at the top of the foam nose strip is flaking and causing particles to be dislodged this relates to eight lots:

- 0408HLP09
- 0422HLP09
- 0428HLP09
- 0520JLP09
- 0520LLP02
- 0517JLP09
- 0506ALP10
- 0520JLP09.

Not all masks in these lot numbers are defective. We are aware that three of the complaints relate to lot 0517JLP09.

Identifying Issues:

The first fault has been identified by the stitching coming away from the ties.

The second fault has been identified on the foam nose strip which breaks down with the application of a small amount of pressure and friction causing particles to be dislodged.



Next Steps:

- Please check your stock of Cardinal Type IIR masks to identify whether it contains
 the lots referred to above and whether they have been affected. Please also be
 vigilant to these issues across remaining lots.
- For all general enquiries for the PPE Dedicated Channel, call Customer Services on 0800 876 6802